

E4RS II EVO - Tip 14: Rear Upright Fixation Screw

Many drivers have already been frustrated by a rear upright fixation hole damaged by a overtighten grub screw.

A very easy way to avoid this problem is simply to replace the 3mm grub screw by a longer one (4mm).

I'm very satisfied by this easy modification; as I never got any defective rear upright since I changed the 3mm grub screw by a 4mm one (TM126304S).

