

Tip 2: Left Side Main Shaft Holder

Test on shaft left mounts (503109 / 503270)



With the original 503109 part, the car is too hard, due to the lack of flex. We tried to run without the 503106 linkage post, it goes really better, but the chassis don't will appreciate for long. We also tried with the 503270 plastic version, it is a bit better but not sufficient. So, I cut the 503109 part with my Dremel; it's a lot better - **really better**.

The flex obtained increases the rear end's overall grip. To obtain a more symmetrical flex, I highly recommends to modify the motor mount.