

### Tip 5: Front Shock Tower

Out of the box, the front shocks can't work correctly: all their movements are blocked / forced by the front shock tower ! To fix this problem, I just have cut the front shock tower, approximately 1mm under the pivot holes.



Now, my front shocks are working perfectly.

